



https://www.plexonline.com/609b12f5-bd1c-401f-831c-29d7676fa070/Plexus_Control/Report_View_Viewer_2.asp?URL=https://www.plexonline.com/609b12f... 1/1

1915

Inspection Sheet Complete

RA436

Customer QA Ref #

0

Part Number	Original Batch / Serial # / Ctrl #	Original Revision #	Quantity	Part Complete	Rev/CHG Current	New Paperwork	New Labels	Disposition	Original Container #	New (Receiving) Serial #	New Job #	Work order Instructions
RBEM621A1001101 S5330	S102884		1	☒ es	☒ es	☐ es	☒ es	DAMAGED/REPAIRABLE	S102884	S109307		Part returned with no damage but there is rust on subcomponent part RBEM621A1001101 S5330-23. Disassemble, remove rust, re- assemble, return in stock. I.D. with new batch at Rev B.
Used MISC line			0	☐ es	☐ es	☐ es	☐ es					Need to change Quarantined item back to stock- was never system shipped
0			0	☐ es	☐ es	☐ es	☐ es					
0			0	☐ es	☐ es	☐ es	☐ es					
0			0	☐ es	☐ es	☐ es	☐ es					
0			0	☐ es	☐ es	☐ es	☐ es					

QC Approval: AT

Date: 8-Nov-18

Special Return/Rework Instructions:

